4

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1.2	neral Information
1.	Report Time Period: From (mo./yr.) 01/03 To (mo./yr.) 12/03
. 2.	DOGM File Number (Mine No): M /370/006
3.	Mine Name: RIM - COLUMBUS MINE
4.	Mineral(s) Mined (or permitted to mine): URANIUM AND VANADIUM.
5.	Type of mine ☐ Surface Mine or Underground Mine
6.	Legal Description (Location of Lands Affected):
	1/4,1/4, NW 1/4, Section 29, Township 3/5, Range 25 E
	1/4,1/4, NW 1/4, Section 30, Township 3/5, Range 25 E
	1/4,1/4,1/4, Section, Township, Range
Nan	ne of Operator or Company: NTERNATIONAL VRANIUM (USA) CORPORATION
8.	Permanent Street Address: 1050 SEVENTEENTH STREET, SVITE 950
	City, State, Zip: DEN VER, CO 80265
	Phone: 303 - 628 - 7798 Fax: 303 - 389 - 4125
9.	Company Representative (or designated operator):
	Name: TERRY V. WETZ
	Title: DIRECTOR OF PROJECT DEVELOPMENT
	Business Address: 1050 SEVENTEENTH STREE, SUITE 950
	City, State, Zip: DENVER CO 80265
	Phone: 303-628-7798 Fax: 303-389-4/25
	Please check if any of the above information has changed since previous year.
Min	ing and Reclamation
IVIIII	ing and Neclamation
1.	Was there any mine related activity during the past year? Yes □ No 🗷
2.	If no - what was the last year of activity? / 1998

SWINING SAS WINING

Reviewed 4 PMB

3.

If yes - how much ore or mineral was mined?

7.	additional surface disturbances that occurred during the past year. No new surface disturbance
5.	How much additional acreage was disturbed during the past year? None
6.	How much acreage was reclaimed during the past year?
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. Two metal-sided buildings, wood frome on concrete slabs, were disassembled: The concrete slabs were left to serve
	removed from the site.
8.	What is the total disturbed acreage of entire project at years end? Appex. 12 acres
9.	Maintain current standby status. No mining or final reclamation activities planned for the coming year.
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .
III. <u>Additiona</u>	al Information - R647-4-121.2 and .3
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.
IV. <u>Signatur</u>	re Requirement
I her	reby certify that the foregoing is true and correct.
	Name (Typed or Print): David C. FRYDENCUND
	Name (Typed or Print): DNID C. FRYDENLUND VIEE PRESIDENT AND GENERAL COUNSEL
	Signature of Operator:
	Date: FEBRUARY 12, 2004
h	

jb
o:\forms\reports\MR-AR